

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

WHITTIER BRIDGE
(Mt. Whittier Bridge)
(Bearcamp Crossing)
Spanning the Bearcamp River
West Ossipee
Carroll County
New Hampshire

HAER NH-50

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Jet Lowe, photographer, October 2009

NH-50-1	West elevation and south portal, looking northeast.
NH-50-2	South portal elevation, looking north.
NH-50-3	Perspective view of east elevation and north portal, looking southwest.
NH-50-4	Elevation of north portal, with Nickerson Mountains in background.
NH-50-5	East elevation, looking west.
NH-50-6	Center panels of Paddleford truss, looking west.
NH-50-7	Underside of deck from south abutment.
NH-50-8	View of original bridge abutments along Bearcamp River, looking northeast.
NH-50-9	Interior view of Paddleford truss with bracing for stabilization, looking south.
NH-50-10	Perspective view of center panels, looking northeast.
NH-50-11	View of roof structure from west portal, looking northeast.
NH-50-12	Interior panel detail near north portal, showing Arnold Graton's sister post repair in 1983.

WHITTIER BRIDGE
HAER NH-50
INDEX TO PHOTOGRAPHS

NH-50-13

Interior view of north portal, looking northeast.